

Japanese Patent Laid-open No. 2001-1230 A

Publication date: January 9, 2001

Applicant: Toyoda Machine Works, Ltd.

Title: MACHINING PROGRAM CREATION METHOD FOR TWO-SPINDLE

5 MACHINE TOOL

10

[0023] The present invention provides a method for creating a NC program for both machining units LM and RM, when the work W mounted on a single table 41 is machined by coordinating two spindle heads 31 and 32. To execute this method, the CPU 51 is provided with, as shown in Fig. 3, software for executing coordination information adding processing 64. The program creation method according to the present invention is performed according to a procedure described below, by changing an operation mode of the CNC unit 50 to a program creation mode.

- [0024] As shown in Fig. 4, as a first stage, a first and a second NC programs NP1 and NP2 for machining the work W are respectively created by individually operating the left and right machining units LM and RM. As the creation order, either the program NP1 or the program NP2 can be created first. Fig. 5 is an example of the both programs NP1 and NP2 for drilling and tapping, in
 association with machining positions a to g of the work W. In the machining example, the program NP1 for the left machining unit LM is formed of eight data blocks with sequence numbers N10 to N80, and programmed so as to drill prepared holes in the process of returning from a machining position d closest to the right machining unit RM to a starting point thereof in order of d → g → c
- 25 → f Likewise, the program NP2 for the right machining unit RM is formed of eight data blocks with sequence numbers N10 to N80, and programmed so as to perform tapping with respect to the prepared holes in the process of moving toward the opponent, that is, the left machining unit LM, in the same order as the machining sequence of drilling.
- [0025] The both programs NP1 and NP2 are created in an interactive manner such that the operator talks with the CPU 51, for example, by inputting an input

item instructed on a display screen 543 by using the ten keys 542, under execution of the input/output support processing 61. The respective NC programs NP1 and NP2 created in this manner are stored in the memory 52 for each one data block in a well-known EIA code format. For example, commands and data are input to each data block subsequent to a sequence number, in order of a control command (a so-called G code command), spindle-specifying data, target position data, a speed command, an M function command, and a block termination command. The respective NC programs NP1 and NP2 can be created by using a code format other than the EIA code.

5

10

15

20

25

30

[0026] Fig. 6 depicts a program example when the left and right machining units LM and RM take partial charge of a plurality of hole drilling operations. In this case, the NP1 for the left machining unit LM is programmed so as to perform hole drilling sequentially to a group of machining positions shown on the upper side of Fig. 6, in the process of returning from the machining position d closest to the right machining unit RM to the starting point thereof in order of $d \rightarrow c \rightarrow b$ → a. The program NP2 for the right machining unit RM is programmed so as to perform hole drilling sequentially to a group of machining positions shown on the lower side of Fig. 6, in the process of moving toward the opponent, that is, the left machining unit LM. In the respective NC programs shown in Figs. 5 and 6, a rotation speed command of the tool spindle is given to the first block. A tool replacement command is given to the previous stage of the first block of the respective NC programs, but these are omitted in Figs. 5 and 6. Furthermore, in Figs. 5 and 6, in the stage in which the programs NP1 and NP2 for single operation are created, a machining permission command MPC and a machining permission wait command PWC have not been inserted yet.

[0027] As shown in Fig. 4, in the machining program creation method of the present invention, debugging of the respective NC programs NP1 and NP2 is executed as a second stage. An object of the debugging processing DBG1 is to remove a problem (bug) included in the respective NC programs NP1 and NP2 when the respective NC programs are executed separately by the CNC unit 50. This processing can be executed by software simulation for checking program operation by displaying a track of the tool moving with respect to the work W on

the display screen 543 based on the respective NC programs NP1 and NP2, without actually operating the machine tool 10. However, when the debugging is to be performed more reliably, the respective NC programs NP1 and NP2 are actually executed by the CNC unit 50 separately, to execute checking by moving the tool with respect to the work W. In this case, a no-load running test in which the tool is not brought into contact with the work W can be used, however, when trial machining in which the work W is machined by the tool is performed, the dimension of the work W, which has been subjected to the trial machining, is measured, to determine the quality of the NC programs NP1 and NP2.

5

10

15

20

25

30

[0028] Subsequent to the debugging DBG1 for executing the respective NC programs NP1 and NP2 individually, in the third stage, coordination information is added to the NC programs NP1 and NP2 for operating the both machining units LM and RM simultaneously in coordination with each other. This processing is explained with reference to Figs. 5 and 6. In the case of Fig. 5 in which drilling and tapping are assigned to the both machining units LM and RM, a plurality of machining permission commands MPC individually identified are added to the first NC programs NP1, which precedes the machining operation (hereinafter occasionally referred to as preceding machining program), and a plurality of machining permission wait commands PWC individually identified are added to the second NC programs NP2, which starts the machining operation tardily (hereinafter occasionally referred to as subsequent machining program). Addition of the machining permission commands MPC and the machining permission wait commands PWC is carried out in the following manner. That is, the data blocks in the subsequent machining program NP2 is sequentially selected as a comparison reference, the comparison reference block is compared with a data block to be compared of the preceding machining program NP1, which is sequentially selected, and the machining permission commands MPC and the machining permission wait commands PWC are added based on the comparison result.

[0029] More specifically, the top data block "N10 d machining" of the subsequent machining program NP2 is selected as the comparison reference

block. Furthermore, as the data block to be compared, the first data block "N10 d machining", the second data block "N20 g machining", the third data block "N30 c machining", and the fourth data block "N40 f machining", of the preceding machining program NP1, are sequentially selected. When an interval between target positions on an X axis of the selected both blocks is equal to or smaller than a predetermined value K for avoiding interference, it is determined that there is an interference, and when the interval is equal to or larger than the predetermined value K, it is determined that there is no interference. The predetermined value K is preset to a value, at which even if a distance in the left and right direction between the spindles 29 and 40 of the both spindle heads 31 and 32 reaches this value, there is a slight space between the opposite side faces of the both spindle heads 31 and 32. As for the selected block of the preceding machining program NP1, if the block is near the top block, it is determined that there is interference. However, in the process of shifting the selected block toward the last block side, a block determined to have no interference is extracted. When this determination changes, a machining permission command MPC-d for permitting execution of the top block of the subsequent machining program NP2 is inserted into the previous stage of the block "N50 b machining", for which determination changes to "no interference". Furthermore, a machining permission wait command PWC-d, which is released due to execution of the machining permission command MPC-d, is inserted into the previous stage of the top block "N10 d machining" of the subsequent machining program NP2.

5

10

15

20

25

30

[0030] The comparison reference of the subsequent machining program NP2 is then shifted to the next block "N20 g machining", and the block to be compared of the preceding machining program NP1 is selected and shifted in order of the first block "N10 d machining", the second block "N20 g machining", the third block "N30 c machining", and the fourth block "N40 f machining". In this process, as shown in Fig. 5, a block "N60 e machining", which is determined to have no interference, is extracted, and a machining permission command MPC-g for permitting execution of the block "N20 g machining" of the subsequent machining program NP2 is inserted into the previous stage of the block "N60 e

machining". Furthermore, a machining permission wait command PWC-g, which is released due to execution of the machining permission command MPC-g, is inserted into the previous stage of the block "N20 g machining" of the subsequent machining program NP2. Thus, by repeating the above processing, in an example of Fig. 9, machining permission commands MPC-c and MPC-f are respectively inserted into the previous stages of the blocks N70 and N80 of the preceding machining program NP1, and machining permission wait commands PWC-c and PWC-f are respectively inserted into the previous stages of the blocks N30 and N40 of the subsequent machining program NP2. [0031] The machining permission commands MPC-d to MPC-f can be instructed by various types of signs. For example, these commands are input by codes of "\$1 to \$4", which is a combination of dollar sign and an identification figure. Furthermore, the machining permission wait commands PWC-d to PWC-f can be also instructed by various types of signs. For example, these commands are input by codes of "¥1 to ¥4", which is a combination of sign ¥ and an identification figure. In this manner, the first and the second NC programs NP1 and NP2 for individual operation created by assuming that the left and right machining units LM and RM are individually operated to perform machining are modified for the coordinated operation of the both machining units. As a result, programs NP1R and NP2R for coordinated operation are created. [0032] After the coordination information adding processing, second debugging DBG2 is executed as a fourth stage, as shown in Fig. 4. In the debugging DBG2, the CNC unit 50 executes the first and the second modified NC programs NP1R and NP2R for the coordinated operation simultaneously in parallel, to remove bugs in the both NC programs NP1R and NP2R under the state that the left and right machining units LM and RM are cooperatively operated. Since bug removal has finished in the second stage with respect to the programs NP1 and NP2 for individual operation, bugs found in the fourth stage can be determined as being due to the coordination information adding processing for the coordinated operation. As a result, the second debugging DBG2 in the fourth stage can be executed easily. When the modified programs NP1R and NP2R are executed by the CNC unit 50, the unit releases the sign

5

10

15

20

25

¥ corresponding to the identification figure, that is, the machining permission wait command PWC every time the unit decodes the respective ¥ signs, and starts NC execution processing 62 with respect to the block in the next stage of the sign ¥.

5

10

15

20

25

30

[0033] The main feature of the method according to the present invention is that the method includes a process for creating the individual machining programs NP1 and NP2 for respective units for individually operating the both machining units, and adding the coordination information to the individual machining programs for the coordinated operation in the next stage, at the time of creating the NC programs for operating the left and right machining units LM and RM cooperatively. In this case, respective NC programs NP1R and NP2R modified for the coordinated operation include the coordination information for the coordinated operation, but are maintained as separate programs. Accordingly, there is such an advantage that when one of the machining units (for example, LM) has a failure, the program (NP2) for individual operation created for the other machining unit (RM) and maintained is used, or the information (PWC) added for the coordinated operation is removed from the program (NP2R) for the coordinated operation for this unit and the program is used, to perform machining in the individual operation by the other machining unit. The method of the present invention has an additional feature in that after the machining programs NP1 and NP2 for individual operation are created, debugging processing DBG1 is executed for these programs, and after the machining

programs NP1R and NP2R for coordinated operation are created, debugging processing DBG2 is executed for these programs, thereby facilitating extraction and removal of bugs.

[0034] The coordination information adding processing 64 can be manual processing performed by an operator or a programmer by operating an input/output unit 54. However, the present invention has such an additional feature that software for making the CNC unit 50 execute the adding processing is incorporated in a system program STM of the CPU 51. Since the CNC unit 50 executes the adding processing 64 to realize automization, the burden on the operator in creating the NC programs is reduced to the same level as that

when the machining units LM and RM are individually operated. As a result, remarkable technical progress can be realized such that the difficulty and induced program errors accompanying the conventional program creation method at the time of executing coordinated operation of the two machining units LM and RM can be eliminated. [0035] Fig. 7 is a flowchart of interference preventing processing constituting a part of the coordination information adding processing 64 shown in Fig. 3. When the operator inputs an execution command of the processing by operating the input/output unit 54, in the state that the NC programs NP1 and NP2 for individual operation are stored in the memory 52, the CPU 51 starts this processing. At first, at step S1, it is determined which one of the left and right machining units LM and RM is to execute the machining operation precedingly. This determination is performed by checking an X-axis target value of respective data blocks after the second block of one or both of the NC programs NP1 and NP2. Specifically, the CPU 51 determines a machining unit in which the X-axis target value shifts in a direction of returning to the own starting point as the preceding machining unit, and a machining unit in which the X-axis target value shifts in a direction going away from the own starting point as the subsequent machining unit. In the program example shown in Fig. 5, since the X-axis target values at a plurality of machining positions d, g, c, f, b, e, and a return to the starting point sequentially, the first NC program NP1 determines the left machining unit LM executing this as the preceding machining program NP1. Furthermore, since the X-axis target values at the machining positions d, g, c, f, b, e, and a move away from the starting point sequentially, the second NC program NP2 determines the right machining unit RM executing this as the subsequent machining program NP2. [0036] When the left machining unit LM is determined to perform the preceding machining, memory areas ML and MR for storing the first and the second NC programs NP1 and NP2 respectively are set as an area B to be compared and a comparison reference area A (step S2). On the contrary, when the right machining unit RM is determined as the preceding machining, memory areas ML and MR are set as the comparison reference area A and the area B to be

5

10

15

20

25

compared (step S3). Addresses Ai and Bi of the both areas A and B are set to the first address of these areas (step S4). In Fig. 5, an initial value is expressed as address 0, but these addresses correspond to the first address of the areas A and B. Subsequently, the NC data blocks to be stored in the addresses Ai and Bi are read (steps S5 and S6), to determine interference between the left and right spindle heads 31 and 32 from the X-axis target value in these blocks (step S7). That is, it is assumed that the left and right spindle heads 31 and 32 are positioned simultaneously in these positions of the target value, and at this time, it is determined whether the spindle heads 31 and 32 physically come in contact with or collide with each other. This determination is specifically performed in the following manner. That is, absolute feed positions XL and XR of the spindle heads 31 and 32, using these starting points as a point of origin, is subtracted from a pre-measured distance XT between these left and right starting points, and when the difference is smaller than the predetermined interference threshold K, it is determined that there is an interference, and when the difference is larger than the predetermined interference threshold K. it is determined that there is no interference. The X-axis target value in the NC programs NP1 and NP2 for the left and right machining units is defined by assuming that the respective own starting points are 0 point, and designating a shift amount from the 0 point toward the other machining unit as a positive absolute amount. [0037] When it is determined that there is an interference, the address Bi of the area to be compared is incremented by one address (step S8), and it is determined whether the data block at this new address is the last block (EOB) (step S9). When it is not the last block, the data block at the new address is read (step S6), and interference check is executed based on the read data block and the data block at the address Ai of the comparison reference area (step S7). Thus, the respective NC data blocks for the subsequent machining unit are designated as the comparison reference, and all NC data blocks for the preceding machining unit (blocks to be compared) are sequentially compared therewith.

5

10

15

20

25

[0038] In the program example in Fig. 5, when the right spindle head 32 performs tapping at position d, steps S6 to S9 are repetitively executed so as to check at which position of d, g, c, f, b, e, and a the left spindle head 31 that performs drilling interferes with the right spindle head 32. Consequently, when it is determined that there is an interference, the address Bi of the area to be compared is sequentially incremented simply, to change the data block in the first NC program NP1 in order of N10, N20, N30, N40, When the data block at the address Bi of the area to be compared is changed to the one defining drilling at the position b, the relationship of XT-SL-XR>K is realized, and it is determined that there is no interference (step S7).

[0039] When it is determined that there is no interference, the first permission wait command ¥1 is inserted into the previous stage of the comparison reference address Ai, that is, the previous stage of the data block N10 for

described above.

wait command ¥1 is inserted into the previous stage of the comparison reference address Ai, that is, the previous stage of the data block N10 for tapping at position d, and the first permission command \$1 is inserted into the previous stage of the address Bi to be compared, that is, the previous stage of the data block N50 for drilling at position b (step S10). After this processing, the comparison reference address Ai is advanced by 1 (step S11), and it is determined whether the updated comparison reference address Ai is the last data block (step S12). When it is not the last block, the address Bi to be compared is cleared to an initial value (step S13). Thereafter, control returns to step S5, to read the NC data block at the updated comparison reference address Ai, and comparison between the second data block for tapping of the second NC program NP2 for subsequent machining and the respective data blocks in the first NC program NP1 for preceding machining is executed as

[0040] By performing the processing as described above, in the machining example in Fig. 5, a second permission wait command ¥2 and a second permission command \$2 are respectively inserted into the previous stage of the data block defining the machining of tapping and drilling, so that simultaneous machining of tapping at position g and drilling at position e are permitted. A third permission wait command ¥3 and a third permission command \$3 are respectively inserted into the previous stage of the data block defining tapping

at position c and drilling at position a, and further, a fourth permission wait command ¥4 and a fourth permission command \$4 are respectively inserted into the previous stage of the data block defining tapping at position f and an original position returning data block of the left machining unit LM that performs preceding machining. In the flowchart of Fig. 7, when the block is determined to be the last block at step S9, control returns to step S5 after step S13. However, when the determination result is Yes at step S9, the control flow can be finished as shown by broken line, in order to omit further processing. [0041] A program creation method when the left and right machining units LM and RM coordinate with each other to machine the work W at respective indexed positions of the rotation table 41 is explained next, with reference to Figs. 8 to 10. Fig. 8 depicts the relationship between the first and the second individual machining NC programs NP1 and NP2 for the left and right machining units individually created and the indexed surfaces L1 to L3 of the work W. In the respective NC programs NP1 and NP2, a table indexing command for directing one machined surface toward the spindle heads 31 and 32 is defined as an independent data block in the previous stage of a group of data blocks for machining the machined surface of the work W. Specifically, there are one data block indexing a first machined surface L1 of the work W to a machining position facing the spindle heads 31 and 32, a group of data blocks for the first machined surface L1, one data block indexing a second machined surface L2 to a machining position, a group of data blocks for the second machined surface L2, one data block indexing a third machined surface L3 to a machining position, a group of data blocks for the third machined surface L3, and lastly, one data block indexing the first machined surface L1 again to the machining position as carrying-out preparation of the work. [0042] The data blocks in each group for machining the same machined surface of the work W correspond to the programs NP1 and NP2 explained with reference to Figs. 5 and 6. In this stage, however, the machining permission command \$1, \$2, ... and the machining permission wait command ¥1, ¥2, ... paired therewith have not yet been inserted. Preferably, in a type using a known pallet changer to automatically change a work pallet on the rotation table

5

10

15

20

25

41, a pallet carrying-in command is defined as an independent data block in the forefront stage of respective NC programs NP1 and NP2, and a pallet carryingout command is defined as an independent data block in the final stage thereof. [0043] In the respective NC programs NP1 and NP2 for individual machining created in this manner, a command for indexing the rotation table 41 at the same position in the same order of the table indexing operation is defined in an overlapping manner. After the CNC unit 50 issues a command so as to index the rotation table 41 to one position according to one of the NC programs, if a drive circuit DUB is instructed to index the rotation table 41 to the same position according to the other NC program, an error occurs in the indexing operation. Therefore, it is necessary to modify these individual machining NC programs NP1 and NP2 for coordinated operation, and the CNC unit 50 executes the coordination information adding processing 64 shown in Fig. 3. [0044] Fig. 9 is an explanatory diagram of the outline of the whole coordination information adding processing 64 executed by the CNC unit 50. Specifically, the coordination information adding processing 64 includes approximately three types of processing. In the first processing, the preceding machining unit and the subsequent machining unit are determined in the same processing as at step S1 in Fig. 7 based on the data block group for the same machined surface, table indexing commands IA to IC in the previous stage of the data block group for one machining unit subjected to the subsequent machining and the last indexing command ID for returning the table are invalidated, and an indexing completion wait command IWC is inserted into the previous stage of the respective data block groups. In the program example in Fig. 9, the first and the second NC programs NP1 and NP2 for the left and right machining units respectively includes a first to a third program units LP1 to LP3, RP1 to RP3, which execute machining operation in three same indexed positions. The program units LP1 to LP3 in the first NC program NP1 is programmed so as to allow the machining operation of the left machining unit LM to precede that of the right machining unit RM according to the program units RP1 to RP3. Therefore, in this program example, all indexing commands IA, IB, IC, and ID overlapping on the indexing commands specified in the NC program NP1 for the

5

10

15

20

25

left machining unit LM are removed or invalidated. Furthermore, the indexing completion wait command IWC is inserted into the next stage of the respective invalidated indexing commands IA, IB, and IC, excluding the last indexing command ID. Preferably, in this processing, an indexing wait release command MIC for releasing the corresponding indexing completion wait command IWC is inserted into the respective next stage of the remaining table indexing commands IA to IC.

5

10

15

20

25

30

[0045] The second processing in the coordination information adding processing 64 includes adding a machining completion wait command MWC instructing not to execute the next indexing command of the rotation table 41, unless all machining operations by the left and right machining units LM and RM are completed on the same machined surface, and a machining wait release command MMC for releasing the machining completion wait command MWC. [0046] Specifically, the machining completion wait command MWC for

confirming completion of machining at the indexed position by one of the NC programs is inserted into one block in the previous stage of respective indexing commands IB, IC, and ID for indexing the rotation table left in the other NC program to the next indexed position, and the machining wait release command MMC for releasing the corresponding machining completion wait command

MWC is inserted into the other NC program. The third processing is insertion processing of the machining permission wait command and the machining permission command between corresponding groups of NC data blocks for preventing interference between the left and right spindle heads 31 and 32, when the left and right machining units LM and RM cooperatively machine the same machined surface. This processing is executed as described above with reference to Figs. 5 to 7.

[0047] The table indexing commands IA, IG, IC, and ID are left in the first NC program NP1 for the left machining unit and the table indexing operation is controlled by this program. In the second processing, therefore, the machining completion wait command MWC for waiting for the completion of machining according to the program units RP1, RP2, and RP3 is inserted into the next stage of corresponding respective program units LP1, LP2, and LP3.

Furthermore, the machining wait release command MMC for releasing the machining completion wait command MWC is inserted into the next stage of corresponding respective program units RP1, RP2, and RP3. In the third processing, the machining permission wait command PWC and the machining permission command MPC for coordinated operation are added to the data block group of the corresponding to program unit in the manner described above.

5

10

15

20

25

30

[0048] When a part of the program units in the second NC program NP2, for example, RP2 is designated for the preceding operation, different from the program example in Fig. 9, the indexing command IB in the program unit RP2 is left in the first processing, and the indexing wait release command MIC is inserted into the next stage, as shown by chain line. On the other hand, the indexing command IB in the corresponding program unit LP2 of the NC program NP1 is removed or invalidated, and the indexing completion wait command IWC is inserted, as shown by chain line, into the previous stage of the data block group Lc following the indexing command. Furthermore, in the second processing, the machining permission wait command MWC is inserted into the next stage of the second program unit RP2, and the machining wait release command into the next stage of the second program unit LP2, respectively, as shown by chain line. As a result, the indexing command of the rotation table 41 can be provided only from one NC program NC1, as shown in Fig. 9, or the program unit that provides the indexing command can be changed for each program unit, so that the work load of the machining unit that performs preceding machining, that is, the work load shared by the left and right machining units LM and RM can be made substantially equal. [0049] Fig. 10 is a flowchart for allowing the CPU 51 in the CNC unit 50 to

execute the coordination information adding processing 64 including the above-described first to third processing. When execution of the processing 64 is instructed by the operator, the first and the second NC programs NP1 and NP2 for individual machining are divided in a unit of indexing command (step S21). Specifically, as shown by broken line in Fig. 9, in each program, one indexing command and the one or more program units following this are divided as one

group, and a top memory address for storing the NC data in each group is stored. A division number Dn is then set (step S22), and in the program example in Fig. 9, Dn=3 is set.

5

10

15

20

25

30

[0050] Subsequently, a processing group pointer Pn is set to an initial value "1" (step S23), to specify LP1 and LP2 as the first program units in the subsequent processing. Thereafter, it is determined whether the pointer Pn exceeds the division number Dn, that is, whether the processing has been completed for all groups (step S24), and when the processing has been completed, the processing based on the flowchart finishes. When the coordination information adding processing 64 has been not yet completed, it is determined whether the first and the second NC programs NP1 and NP2 both have the program unit at the first indexing position specified by the pointer Pn (step S25). When only one of the NC programs has the program unit, that is, it is determined that the machining operation only for one of the machining units is programmed at that table indexing position, control jumps to step S34, where 1 is added to the pointer Pn to specify the second program unit, and then returns to S24. Therefore, when it is programmed, at each indexed position of the table 41, so that only one machining unit individually performs machining, any modification is not carried out with respect to the program unit that specifies the indexing position.

[0051] However, when the program unit for allowing the left and right machining units LM and RM to perform machining operation at each indexed position is present in both NC programs NP1 and NP2, it is determined which machining unit performs preceding machining (step S26). This determination is performed in the same manner as the processing at step S1 shown in Fig. 7. When it is determined that the left machining unit LM performs preceding machining, the indexing command IA in the program unit RP1 for the right machining unit RM is deleted or invalidated (step 27). The indexing completion wait command IWC is then inserted into the next stage of the indexing command IA, and the indexing release command MIC is inserted into the next stage of the left indexing command IA (step S28). Furthermore, the machining completion wait command MWC for confirming the completion of machining operation according

to the program unit RP1 for the right machining unit RM is inserted into the end of the program unit LP1 for the left machining unit LM, and the machining wait release command MMC is inserted into the end of the program unit RP1 (step S29). On the contrary, when it is determined that the right machining unit RM performs preceding machining, the indexing command IA in the program unit LP1 for the left machining unit LM is deleted or invalidated (step 30). The indexing completion wait command IWC is then inserted into the next stage of the indexing command IA, and the indexing release command MIC is inserted into the next stage of the left indexing command IA in the program unit RP1 (step S31). Furthermore, the machining completion wait command MWC is inserted into the end of the program unit RP1, and the machining release command MMC is inserted into the end of the program unit LP1 (step S32). [0052] Subsequent to step S29 or S32, the interference preventing processing is executed based on the flowchart in Fig. 7 (step S33). As a result, when the program units LP1 and RP1 for the left and right machining units LM and RM are executed by the CNC unit 50, these program units LP1 and RP1 are modified so that the left and right machining units LM and RM are cooperatively operated, and a part of the end of the machining operation of the preceding unit and a part of the start of the machining operation of the subsequent machining unit are executed simultaneously in parallel, in the state that the both spindle heads 31 and 32 do not interfere with each other in the direction of X axis. When the interference preventing processing at step S33 is completed, the pointer Pn is advanced (step S34). As a result, the second program units LP2 and RP2 are specified as the next object to be modified, and processing at steps S25 to S33 is executed again for the second program units LP2 and RP2. After the coordination information adding processing with respect to the second program units LP2 and RP2, the pointer Pn specifies the third program units LP3 and RP3 (step S34). Therefore, when the processing at steps S25 to S33 is executed again, the third program units LP3 and RP3 are modified, and the coordination information relating to the indexing of the rotation table 41 is added as shown in Fig. 9.

5

10

15

20

25



(19)日本国特許庁(JP)

(12) 公開特許公報(A)

(11)特許出願公開番号 特開2001-1230

(P2001-1230A)

(43)公開日 平成13年1月9日(2001.1.9)

(51) Int.Cl. ⁷	
B 2 3 Q	15/00

G 0 5 B 19/4093

識別記号 301

B 2 3 Q 15/00

FΙ

テーマコート*(参考) 301J 5H269

303

303Z

G05B 19/4093

E

審査請求 未請求 請求項の数6 OL (全 16 頁)

(91)	யண்ணப
(21)	出願番号

特顧平11-174218

(71)出顧人 000003470

豊田工機株式会社

(22)出願日 平成11年6月21日(1999.6.21) 愛知県刈谷市朝日町1丁目1番地

(72)発明者 堀田 尊之

愛知県刈谷市朝日町1丁目1番地 豊田工

機株式会社内

(72)発明者 加藤 友也

愛知県刈谷市朝日町1丁目1番地 豊田工

機株式会社内

Fターム(参考) 5H269 AB01 AB03 AB06 CC02 CC13

CC15 DD01 EE01 EE07 KK10


QB06 QC01

(54) 【発明の名称】 2主軸ヘッド工作機械用の加工プログラム作成方法

(57)【要約】

【課題】 協調運転動作される左右加工ユニット用の第 1及び第2加工プログラムの各々を互いに他の加工ユニ ットの動作を考慮せずに作成できるようにすること。

【解決手段】 第1ステップでは、左右の加工ユニット を単独運転するための第1及び第2NCプログラムNP 1、NP2をそれぞれ個別に作成する。第2ステップで は、これらプログラムをCNC装置に個別に実行させ、 単独運転における各プログラム中の不具合を抽出・修正 する第1のデバグ処理DBG1を行う。第3ステップで は、第1のデバグを行った両プログムを同時並行的に実 行させるための協調情報をCNC装置により自動的に両 プログラムに付加して協調運転用の第1及び第2NCプ ログラムNP1R、NP2Rを作成する。第4ステップ では、これら協調運転用の両プログラムをCNC装置に 実行させて、協調運転における両プログラム中の不具合 を抽出・修正する第2のデバグ処理DBG2を行う。



【特許請求の範囲】

【請求項1】 2台の主軸ヘッドの各々を共通の移動範 囲内で独立して移動すると共にこの移動方向を横切る方 向に独立して移動し、前記共通移動範囲の中間位置で前 記主軸ヘッドの前方に配置した単一のテーブル上のワー クの複数の加工個所を前記2台の主軸ヘッドがそれらに 取り付けた工具を用いて協調して加工するための2主軸 ヘッド工作機械用加工プログラムの作成方法であって、 加工動作を先行する一方の主軸ヘッドが前記複数の加工 個所を他方の主軸ヘッドの起点側から自身の起点側に向 かって復帰する途中で順次加工するための複数のデータ プロックからなる先行加工プログラムを作成する第1加 エプログラム作成ステップと、前記一方の主軸ヘッドの 加工動作に後続する前記他方の主軸ヘッドが前記複数の 加工個所又は他の複数の加工個所を自身の起点側から前 記一方の主軸ヘッドの起点側に向かって移動する途中で 順次加工するための複数のデータブロックからなる後続 加工プログラムを作成する第2加工プログラム作成ステ ップと、前記一方の主軸ヘッドが実行する複数の加工個 所に対する加工動作の一部と前記他方の主軸ヘッドが実 20 行する前記複数の加工個所又は前記他の複数の加工個所 に対する加工動作の一部とを並行動作させるように前記 第1及び第2加工プログラム作成ステップで作成された 前記先行及び後続加工プログラムの両方に協調運転のた めの協調情報を付加する協調情報付加ステップと、から なることを特徴とする加工プログラム作成方法。

【請求項2】 請求項1に記載の方法において、前記協調情報付加ステップは前記工作機械を制御するCNC装置が実行する自動処理ステップであることを特徴する加工プログラム作成方法。

【請求項3】 請求項1又は2に記載の方法において、前記先行プログラムに従う前記一方の主軸ヘッドの移動と前記後続加工プログラムに従う前記他方の主軸ヘッドの移動とを個別に実行して前記先行及び後続加工プログラムの不具合を修正する単独加工デバグステップを前記協調情報付加ステップに先立って実行し、また、前記協調情報付加ステップの後に、前記先行及び後続加工プログラムを並行して実行し前記2台の主軸ヘッドの移動を協働運転して前記先行及び後続加工プログラムの協調加工動作における不具合を修正する協調加工デバグステップを実行することを特徴とする加工プログラム作成方法。

【請求項4】 請求項1~3の何れか1項に記載の方法において、前記協調情報付加ステップは、前記後続加工プログラムの前半の一部の実行を待機させる加工許可待命令を前記後続加工プログラムの前半部に挿入すると共に前記加工許可待命令を解除する加工許可命令を前記先行加工プログラムの後半部に挿入することからなることを特徴とする加工プログラム作成方法。

【請求項5】 2台の主軸ヘッドの各々を共通の移動範 50

囲内で独立して移動すると共にこの移動方向を構切る方 向に独立して移動し、前記共通移動範囲の中間位置で前 記主軸ヘッドの前方に配置した単一の回転テーブル上の ワークの複数の加工個所を前記2台の主軸ヘッドがそれ らに取り付けた工具を用いて協調して加工するための2 主軸ヘッド工作機械用加工プログラムの作成方法であっ て、前記回転テーブルを複数の割出位置に順次割り出す 複数の割出命令を定義すると共にこれら割出命令の各々 に続いて前記主軸ヘッドの一方に前記ワーク上の複数の 加工個所を加工させるための第1加工プログラムを定義 する第1加工プログラム作成ステップと、前記回転テー ブルを複数の割出位置に順次割り出す複数の割出命令を 定義すると共にこれら割出命令の各々に続いて前記主軸 ヘッドの他方に前記ワーク上の前記複数の加工個所又は 他の複数の加工個所を加工させるための第2加工プログ ラムを定義する第2加工プログラム作成ステップと、前 記第1及び第2加工プログラムに前記回転テーブルを同 一割出位置に割り出す割出命令データが回転テーブルの 同一割出順位に重複して存在するときは前記第1及び第 2加工プログラムの一方に定義される前記重複する割出 命令を無効にするプログラム修正ステップと、からなる ことを特徴とする加工プログラム作成方法。

【請求項6】 請求項5に記載の方法において、前記プログラム修正ステップにおいて前記重複する割出命令が無効にされるときは協調情報をさらに付加し、この協調制御情報を付加する処理は、前記第1及び第2加工プログラムの一方に残された前記割出命令に基づいて前記回転テーブルが割出されたことを確認するために割出完了待命令を他方の加工プログラムの前記無効にされた割出命令に続く加工プログラムの前段に付加する操作と、前記無効化にされた割出命令に続く加工プログラムに基づく加工動作の完了を確認するために加工完了待命令を前記無効化された割出命令が残された加工プログラムの末尾に付加する操作と、前記加工完了待命令を解除する命令を前記無効化された割出命令に続く加工プログラムの末尾に付加する操作と、からなることを特徴する加工プログラム作成方法。

【発明の詳細な説明】

[0001]

30

40

【発明の属する技術分野】本発明は、数値制御工作機械に使用される例えばNCプログラムで代表される加工プログラムの作成方法に関し、更に詳しくは、単一のワークに対し独立して運動できる2台の主軸ヘッドが協調して加工動作する加工プログラムの作成方法に関する。

[0002]

【従来の技術】単一のワークに対し2台の主軸ヘッドが独立して移動して加工を施す公知の数値制御工作機械においては、2台の主軸ヘッドの運動は別個の加工プログラムに従って制御される。従来、このような加工プログラムを作成する際、プログラマは、一方の主軸ヘッドの

運動制御のための第1加工プログラムを他方の主軸へッドの運動を勘案して作成し、また他方の主軸へッドの運動制御のための第2加工プログラムを前記一方の主軸へッドの運動を勘案して作成している。具体的には、第1加工プログラムを構成する複数のデータプロックの適切なプロック間及び第2加工プログラムを構成する複数のデータブロックの適切なプロック間に待合わせ情報を挿入し両主軸へッド同士が干渉せずに協調動作するようにしている。

[0003]

【発明が解決しようとする課題】しかしながら、従来のように一方の主軸ヘッドのための第1加工プログラムを他方の主軸ヘッドが行う動作を考慮して作成し、他方の主軸ヘッドが前記第1加工プログラムを前記一方の主軸ヘッドが前記第1加工プログラムに従って行う動作を考慮して作成する方法では、プログラマーに過度の負担を課す面倒なプログラム作業となり、プログラムエラーを誘発し易い。特に、プログラム作成後に実際に工作機械を運動させて行うデバグ作業では、第1及び第2プログラムを同時に実行させて行う必要があるため、同時並グラムを同時に実行させて行う必要があるため、同時並グラムを同時に実行させて行う必要があるため、同時並グラムを同時に実行させて行う必要があるため、同時並グラムを同時でなく、このため両プログラムに含まれるバグの特定が困難となる。

【0004】従って、本発明の主たる目的は、一方の主軸ヘッド用の第1加工プログラムを他方の主軸ヘッドが行う運動を考慮せずに作成でき、また他方の主軸ヘッドの第2加工プログラムを前記一方の主軸ヘッドが行う運動を考慮せずに作成できるようにすると共に、かつプログラム作成後のデバグ作業を容易にすることにある。本発明の他の目的は、両主軸ヘッドを協調運転する加工プログラムを作成する場合の回転テーブルの割出命令の付与に関わる問題を解消することにある。

[0005]

【課題を解決するための手段】上述した課題を解決する ために、請求項1に記載の加工プログラム作成方法は、 2台の主軸ヘッドが移動する共通の移動範囲の中間位置 で前記主軸ヘッドの前方に配置した単一のテーブル上の ワークの複数の加工個所を前記2台の主軸ヘッドがそれ らに取り付けた工具を用いて協調して加工するための2 主軸ヘッド工作機械用加工プログラムの作成方法を提供 する。この方法は、先行する一方の主軸ヘッドが前記複 数の加工個所を他方の主軸ヘッドの起点側から自身の起 点側に向かって復帰する途中で順次加工するための複数 のデータプロックからなる先行加工プログラムと、後続 する他方の主軸ヘッドが前記複数の加工個所又は別の複 数の加工個所を自身の起点側から前記一方の主軸ヘッド の起点側に向かって移動する途中で順次加工するための 複数のデータブロックからなる後続加工プログラムとを 個別に作成する。その後、前記一方の主軸ヘッドが実行 する複数の加工個所に対する加工動作の一部と前記他方 50 の主軸ヘッドが実行する複数の加工個所に対する加工動作の一部とを並行動作させるように前記先行及び後続加工プログラムの両方に協調運転のための協調情報を付加することを特徴とする。

【0006】この加工プログラム作成方法では、最初に一方の主軸ヘッドが実行する先行加工プログラムと他方の主軸ヘッドが実行する後続加工プログラムとを、恰もこれら主軸ヘッドの各々を独立して加工動作するような形で互いに他の主軸ヘッドの動作を考慮せずに作成し、その後に先行加工プログラムの後半の一部と後続加工プログラムの前半の一部とを並行動作させるように両加工プログラムに協調運転のための協調情報を付加するようにした。

【0007】好適な形態として、請求項2に記載される発明は、前記協調運転のための協調情報の付加処理を、工作機械を制御するCNC装置に実行させることを特徴とする。これにより、加工プログラムの作成者への負担を単独運転用のプログラムの作成のみに軽減し、プログラムエラーの発生する機会を減少する。

20 【0008】さらに好適な形態として、請求項3に記載される方法は、単独運転用の加工プログラムを作成した後にこれら加工プログラムに基づいて両主軸へッドを個別に運転して各単独運転用加工プログラムに含まれるバグを除去し、このバグ除去を行った単独運転用加工プログラムに協調運転のための協調情報を付加すると共に、この付加処理の後に両主軸へッドをこの協調加工プログラムに基づいて協調運転させてこの協調運転における協調加工プログラム上のバグを除去することを特徴とする。デバグ作業を単独運転用プログラムと協調加工プログラムと分けて2段階で行い、バグ除去を容易にしかつ短時間で行えるようにする。

【0009】さらに好適な形態として請求項4に記載される発明は、前記協調情報を付加する処理では、前記後 統加工プログラムの前半部の実行を待機させる加工許可 待命令を前記後統加工プログラムの前半部に挿入すると 共に、前記加工許可待命令を解除する加工許可命令を前 記先行加工プログラムの後半部に挿入し、両主軸へッド の加工動作を一部並行動作させて加工能率の向上を図る ようにした。

【0010】請求項5に記載の発明は、2台の主軸へッドが共通経路で移動する2主軸へッド工作機械においてワークを取り付けるテーブルを単一の回転テーブルとした場合に適用される加工プログラム作成方法が提供する。この場合、一方の主軸へッドのための単独加工プログラムを作成する際に、回転テーブルを複数の割出位置へ順次割り出す複数の割出命令を定義すると共に、これら割出命令の各々に続いて第1加工プログラムを定義し、また他方の主軸へッドのための単独加工プログラムを作成する際に、各割出命令の定義に続いて第2加工プログラムを定義する。さらに、協調運転のためのプログ

5

ラム修正においては、前記回転テーブルの割出順序の同 一順位に同一割出位置を指定する割出命令が両加工プロ グラムに重複して存在するか否か判定し、重複する場合 には両加工プログラムの一方の重複する割出命令を無効 にする。

【0011】これにより、2つの加工プログラムが同時期に同一割出位置へ回転テーブルを割り出すような制御上の干渉を排除する。ここで、割出命令を無効にするとは、その割出命令を削除したり、或いはCNC装置がその割出命令を実行せずに無視するように特別な記号を付加する等により実施できる。好適には、前記第1加工プログラム及び第2加工プログラムは、請求項1に定義されるような先行加工プログラム及び後続加工プログラムとし、またプログラム修正処理では請求項1に定義される協調情報の付加処理を行うようにしてもよい。

【0012】好適には、請求項6に記載されるように、 重複する割出命令を無効にする場合、両加工プログラム に協調情報を付加する。具体的には、例えば、第1加工 プログラムの無効にされなかった割出命令に基づいて回 転テーブルの割出完了後に第2加工プログラムの無効に された割出命令に続く加工プログラムが開始されるよう にするため、この加工プログラムの前段に割出完了待命 令を挿入し、また、この加工プログラムに基づく加工動 作の完了を確認するために加工完了待命令を第1加工プログラムの無効にされなかった割出命令に続く加工プログラムの がラムの無効にされなかった割出命令に続く加工プログラムの からの前段に挿入し、さらに、前記加工完了待命令を 解除する命令を無効化された割出命令に続く加工プログラムの未尾に挿入するする。

【0013】これにより、同一割出順位において回転テ ーブルが同一割出位置に割り出された状態では、2つの 主軸ヘッドの加工動作がそれぞれの加工プログラムに従 って異なる時点で開始され異なる時点で終了されても、 それら加工プログラムに基づく2台の主軸ヘッドの加工 動作が完了するまで何れか一方の加工動作が先に完了し ても回転テーブルをその割出位置に維持し、回転テーブ ルの誤動作を排除する。前記割出完了待命令、加工完了 待命令及びこの加工完了待命令を解除する命令を例え ば"M機能"として周知の補助機能命令を用いれば、C NC装置に待合わせ制御のための特別なソフトウエアを 付加せずに回転テーブルの割出しに関連して両主軸ヘッ ドを協調制御できる。前記割出完了待命令と加工完了待 命令は、それぞれ異なる加工プログラムに挿入すること が必要であるが、第1及び第2加工プログラムのどちら に割出完了待命令を付加するようにしてもよい。前記割 出完了待命令は割出命令が無効にされる加工プログラム に挿入するが、この割出完了待命令を解除する命令を割 出命令が有効に残される加工プログラムに挿入するよう にしてもよい。この解除命令を使用しない形態では、回 転テーブルが無効にされた割出命令により指定される回 転位置に割り出されたか否かを確認した後に前記割出完 了待命令を解除するソフトウエアを設けることが好まし い。

[0014]

【発明の実施の形態】以下、本発明の実施の形態を図面に基づいて説明する。図1は、本発明方法を実施する数値制御装置の制御対象である2台の主軸へッド付き工作機械10の正面図を示す。この図において、11は工作機械10のベッドであり、このベッド11の後部上面にガイドウエイ11Gが形成され、これに沿って左右加工ユニットLM、RMを構成する一対のコラム12、13が図において左右方向(X方向)に案内されている。コラム12、13は、それぞれサーボモータ14、15、送りネジ16、17、ナット18、19からなる左右送り機構により左右移動され、ベッド11の片端に設定された自身の送り起点から互いに相手のコラムに向かって前進移動すると共に、逆に相手のコラムから離間して自身の送り起点に向かって後退移動する。

【0015】サドル21、22は、コラム12、13の 内側面で上下に延びるガイドウエイ12G、13Gに沿 って上下方向(Y方向)に移動でき、それぞれサーボモ ータ23、24、送りネジ25、26、ナット27、2 8からなる上下送り機構により上下移動される。主軸へ ッド31、32は、サドル21、22の互いに対向する 側面で図1の紙面垂直方向の水平に延びる前後ガイドウ エイ21G、22Gに沿って前後方向(2方向)に移動 でき、それぞれ図略のサーボモータ、送りネジ35、3 6、図略のナットからなる前後送り機構により前後移動 される。主軸ヘッド31、32は、前後移動方向と平行 に延びるそれぞれの軸線の周りに工具主軸39、40を 回転自在に支持し、それぞれに内蔵したビルトインモー タにより工具主軸39、40を回転駆動できる。工具主 軸39、40は、コラム12、13がそれぞれの起点に 復帰した原位置状態において、図略の自動工具交換装置 により、それらの前端に複数の工具T(図8参照)を選 択的に装着できる。

【0016】回転テーブル41は、工具主軸39、40の前端側のベッド11上で、かつこのベッド11の左右幅方向の中間位置に設置され、図略の割出機構により水平面内で回転割出しされ、その上面に適宜治具を介して取り付けられる単一の工作物Wの各加工面を工具主軸39、40に向けることができる。従って、主軸へッド31、32は、それら間に定義される左右方向の共通の移動経路内でコラム12、13と共に左右移動され、またサドル21、22と共に上下動されて、工具主軸39、40をワークWの加工位置へ位置決めし、それら自身が前後移動して工具主軸39、40前端の図略の工具により、ワークWに加工を施すように動作する。ワークWに対する加工は、工具がドリルの場合では穴明け加工であり、タップの場合では加工済の穴内面にネジ切りを行

30

う。エンドミルの場合では工具とワークWとの当接位置 で主軸ヘッド31,33を単独又は協調して互いに直交 するX, Y及び2方向に同時2軸又は3軸制御してワー クWにコンタリング加工を施すことができる。必要であ れば、回転テーブル41上に複数のワークを取付けるよ うにしてもよい。

【0017】図2は、上記工作機械10を制御する制御 システムを示す。CNC装置50は、主として中央処理 装置(以下、CPUと称する。)51、メモリー52か らなり、メモリー52のROMに記憶されたシステムプ ログラムSTMの制御下で各種演算処理を実行する。メ モリー52のRAMには、第1及び第2数値制御プログラ ム(以下、NCプログラム) NP1、NP2を記憶する 領域、各種信号のオン・オフを記憶するフラッグ領域F LG、後述する各種パラメータやデータK、XT、・・ ・などを記憶するデータ領域および演算処理を実行する ワーキング領域WORKが設けられている。CPU51 は、インタフェース53を介して入力装置54及びシー ケンス制御用のプログラマブル・ロジック・コントロー ラ(以下、PLCと称する。) 55に接続され、これら との間で種々の情報を伝達或いは交換する。入力装置5 4は、各種の命令スイッチ類541、データ入力用のテ ンキー542、表示装置543等からなる。

【0018】また、CPU51は、インタフェース55 を介して駆動装置56に接続される。この駆動装置56 は、左加工ユニットLMのための駆動回路DUX、DU Y、DUZ、右加工ユニットRMのための駆動回路DU U、DUV、DUW、さらには回転テーブル41の割出 しのための駆動回路DUBから構成され、駆動回路DU X、DUY、DUZに接続されたサーボモータ14、2 3、33、駆動回路DUU、DUV、DUWに接続され た15、24、34及び駆動回路DUBに接続されたサ ーボモータ42を制御し、これらモータの回転位置を検 出するエンコーダ141、231、331、151、2 41、341、421から位置帰還出力を受取る。左加 エユニットLMのための駆動回路と右加工ユニットRM のための駆動回路とは、DUXとDUUが、DUYとD UVが、DUZとDUWがそれぞれ対応し、これらは左右 送り制御軸、上下送り制御軸、前後送り制御軸を構成し ている。

【0019】CPU51が実行する処理機能の説明図で ある図3を参照して説明すると、CPU51は、入力さ れるNCプログラム及び各種パラメータをオペレータが 対話形式で入出力装置54からメモリー52の各ユニッ ト用の記憶エリアに記憶できるように支援する入出力支 援処理61と、入力されたNCプログラムを1データブ ロックづつ読取・解読して目標位置、送り速度、制御モ ード等の設定や目標位置までの補間点の演算を行うNC 実行処理62と、設定された目標位置、送り速度、制御

時間毎に到達すべき位置決め点を演算し各制御軸に出力 する移動命令処理63と、を左右の加工ユニットLM, RMの各々について、システムプログラムSTMの制御 下で実行する。入出力支援処理61は、CNC装置51 内で計算或るいは記憶される各種情報を各加工ユニット LM、RM毎に区別して表示画面543に表示させる表 示処理機能も実行する。NC実行処理62は、NCプロ グラムの各データブロックに含まれる工具主軸の回転起 動・停止命令、クーラントのオン・オフ命令、工具交換 命令等のM機能命令(補助機能命令)に関する情報をP LC55との間で所定時間毎に交換する処理機能も含 tr.

8

【0020】CPU51が実行するこれらの処理機能は この種の工作機械を制御するCNC装置が持つ一般的機 能として公知であるので、本発明に関係する処理につい て以下に簡単に説明する。 CPU51の処理時間は、例 えば10ミリ秒のような単位時間毎に左加工ユニット用 処理時間帯と右加工ユニット用処理時間帯とが時間的位 相差を持って交互に割当てられるように時分割されてい る。CPU51は、左加工ユニット用処理時間帯の各々 では、左加工ユニットLMのための第1NCプログラム NP1についてNC実行処置62又は移動命令処理63. を実行し、右加工ユニット用処理時間帯の各々では、右 加工ユニットRMのための第2NCプログラムNP2に ついてNC実行処置62又は移動命令処理63を実行す

【0021】NC制御動作の開始直後及び1データプロ ックの制御動作完了直後の処理時間帯では、CPU51 はNC実行処理62を行い、この処理において、NCプ ログラムNP1、NP2をメモリー52から1データブ ロック単位で読出・解読し、Gコード (制御コード)-命---令、制御軸、目標位置、送り速度等を設定し、輪郭制御 の場合は目標位置までの補間点を演算し、また読出され た1データブロック中にM機能命令が含まれる場合はP LC55とシーケンス制御情報を交換する。CPU51 は、NC実行処理を実行した処理時間帯の単位時間後の 次の同一加工ユニットに割当された処理時間帯では、移 動命令処理63を実行し、設定された各種情報に基づき 前述したコラム12、13、サドル21、22、主軸へ ッド31、32、回転テーブル41などの可動要素がそ のブロックで指定される目標位置に指定された速度で移 動されるように駆動装置56を制御する。

【0022】より具体的には、この移動命令処理63で は、前記各種情報及び指定された制御軸のエンコーダか らの帰還情報に基づきその指定された制御軸がこの割当 時間内に到達すべき通過点を演算し、その駆動回路へ出 力する。単位時間経過後に次の同一加工ユニットに割当 された処理時間帯が始まる時、再び移動命令処理63を 実行し、この移動命令処理63は同一加工ユニットの1 モード等の情報及び補間点情報に基づき各制御軸が単位 50 データブロックで指定された制御軸が目標位置に到達し

てその1データブロックが完了するまで、繰り返し実行される。この1データブロックに基づくNC制御が完了すると、CPU51は、この制御完了した加工ユニットに割り当てられた次の単位時間経過後の処理時間帯において、同一加工ユニットのためのNCプログラムの次の1ブロックデータについてNC実行処理62を行う。なお、入出力支援処理61は、各加工ユニットLM、RMの割当処理時間帯の後半部の空き時間を利用して表示画

【0023】本発明は、上述したように2台の主軸へッド31、32を協調動作させて単一のテーブル41上に取り付けたワークWに加工を施す場合に両加工ユニットLM、RM用のNCプログラムを作成する方法であり、この方法を実施するために、CPU51には図3のように協調情報付加処理64を遂行するためのソフトウエアが付加されている。本発明によるプログラム作成方法は、図4に処理上の特徴が示されており、CNC装置50の動作モードをプログラム作成モードに切り替えて以下の手順で実施される。

面543への表示処理を実行する。

【0024】図4に示すように、先ず、第1段階とし て、左右の加工ユニットLM、RMが単独運転されてワ ークWを加工するための第1及び第2NCプログラムNP 1、NP2を個別に作成する。両プログラムNP1、N P2の作成順序は、どちらを先に作成してもよい。図5 は、下穴及びタップ加工のための両プログラムNP1、 NP2の一例をワークWの加工個所 a ~ g と関連して示 す。この加工例では、左加工ユニットLM用のプログラ ムNP1は、シーケンス番号N10~N80までの8つ のデータブロックで構成され、右加工ユニットRMに近 い加工個所dからd→g→c→f・・・・の順で自身の 起点に復帰する過程で順次下穴を明けるようにプログラ ムされる。一方、右加工ユニットRM用のプログラムN P2は、同様にシーケンス番号N10~N80までの8 つのデータブロックで構成され、相手側つまり左加工ユ ニットLM側に向かう過程で、前記下穴の加工順序と同 一順序でこれら下穴にタップ加工するようにプログラム

【0025】両プログラムNP1及びNP2は、前述した入出力支援処理61の実行の下で、例えば、表示画面543に指示される入力項目をテンキー542により入力することによりオペレータがCPU51と対話する形式で作成される。このように作成される各NCプログラムNP1、NP2は、周知のEIAコードフォーマットで1データブロックづつメモリー52に記憶される。例えば、各データブロックには、シーケンス番号に続き、制御命令(所謂Gコード命令)、軸指定データ、目標位置データ、速度命令、M機能命令、ブロック終了命令の順で命令及びデータが入力される。各NCプログラムは、EIAコード以外のコードフォーマットを用いて作成してもよい。

【0026】図6は、左右加工ユニットLM、RMが複数の穴加工を分担して行う場合のプログラム例を示す。 この場合、左加工ユニットLM用のプログラムNP1 は、同図において上段に示す複数の一群の加工個所に、 右加工ユニットRMに近い加工個所dからd \rightarrow c \rightarrow b \rightarrow

10

右加工ユニットRMに近い加工個所 d から d → c → b → a の順で自身の起点に復帰する過程で順次穴明けするようにプログラムされ、右加工ユニットLM用のプログラムNP 2 は、下段に示す複数の一群の加工個所に、相手側つまり左加工ユニットLM側に向かう過程で、穴明けするようにプログラムされる。なお、図 5 及び図 6 に示す各N C プログラムにおいて、最初のブロックには工具主軸の回転速度命令も与えられる。また、工具交換命令は、各N C プログラムの最初のブロックの前段に与えられるが、これら図 5 及び図 6 では省略されている。さら

に、図5及び図6において、単独運転用のプログラムN

P1、NP2が作成される段階では、加工許可命令MP

C及び加工許可待命令PWCは未だ挿入されてない。

【0027】再び図4に示すように、本発明の加工プロ グラム作成方法は、第2段階として、各NCプログラム NP1、NP2のデバグが実行される。このデバグ処理 DBG1は、各NCプログラムをCNC装置50により 個別に実行した場合にそのNCプログラムNP1、NP 2中に含まれる不具合 (バグ) を除去することを目的と する。この処理は、実際に工作機械10を動作させずに 各NCプログラムNP1、NP2に基づきワークWに対 して移動する工具の軌跡を表示画面543上に表示させ て動作確認するソフトウエアシュミレーションによって も行うことができるが、より確実にデバグを行う場合で は、各NCプログラムNP1、NP2を実際にCNC装 置50により個別に実行させ、ワークWに対し工具を移 動させて実施される。この場合、工具をワークWに対し 接触させない空運転でもよいが、工具によりワークWを 加工する試し加工するときは、試し加工されたワークW の寸法を測定してそのNCプログラムNP1、NP2の 良否を判定できる。

【0028】各NCプログラムNP1、NP2を単独に実行するデバグDBG1に続き、第3段階では、両加工ユニットLM、RMを協調して同時に運転するために両NCプログラムNP1、NP2に協調情報が付加される。この処理は、図5及び図6を参照して説明される。下穴加工とタップ加工を両加工ユニットLM、RMに分担させる図5の場合では、加工動作を先行する第1NCプログラムNP1(以下、時折、先行加工プログラムと称する)に複数の個々に識別される加工許可命令MPCを付加し、加工動作が遅れて開始される第2NCプログラムNP2(以下、時折、後続加工プログラムと称する)に複数の個別に職別される加工許可待命令PWCを付加する。加工許可命令MPC及び加工許可待命令PWCの付加は、後続加工プログラムNP2のデータブロックを比較基準としてプログラム順に順次選択し、この比

較基準プロックを先行加工プログラムNP1の順次選択 される被比較データブロックと比較し、この比較結果に 基づいて行われる。

【0029】より具体的には、後続加工プログラムNP 2の最先データブロック「N10d加工」を比較基準プ ロックとして選択し、また被比較ブロックとして先行加 エプログラムNC1の最初のデータブロック「N10 d加工」、2番目のブロック「N20 g加工」、3番 目のプロック「N30 c加工」、4番目のプロック 「N40 f加工」の順で選択し、選択された両ブロッ クのX軸目標位置の間隔が干渉を回避する所定値K以下 であれば干渉有りと判断し、所定値K以上であれば干渉 なしと判定する。この所定値Kは、両主軸ヘッド31、 32の主軸39と主軸40との間の左右方向における距 離がこの値になった状態でも両主軸ヘッド32、32の 互いの対向側面間に若干の空間ができるような値として 予め設定される。先行加工プログラムNP1の選択プロ ックは、最先プロック近辺のものであれば、干渉有りと 判定されるが、最終プロック側にその選択プロックを移 行する過程において、干渉無しと判定されるブロックが 20 抽出される。この判定が変わるとき、後続加工プログラ ムNP2の最先プロックの実行を許可する加工許可命令 MPC-dを干渉無しに判定が変わるプロック「N50 b加工」の前段に挿入し、また、後続加工プログラム NP2の最先プロック「N10 d加工」の前段に加工 許可命令MPC-dの実行により解除される加工許可待 命令PWC-dを挿入する。

【0030】次に、後続加工プログラムNP2の比較基 準を次段のブロック「N20 g加工」にシフトすると 共に、再び先行加工プログラムNP1の被比較ブロック を最先プロック「N10 d加工」、2番目のプロック 「N 2 0 g加工」、3番目のブロック「N 3 0 c加 工」、4番目のプロック「N40 f加工」の順で選択 してシフトする。この過程において、図5に例示される ように、干渉無しと判定されるプロック「N60 e加 工」が抽出され、のプロックの前段に後続加工プログラ ムNP2のブロック「N20 g加工」の実行を許可す る加工許可命令MPC-gを挿入し、また後続加工プロ グラムNP2のプロック「N20 g加工」の前段にこ の加工許可命令により解除される加工許可待命令PWC 一gを挿入する。このようにして、上述した処理を繰り 返すことにより、図9の例では、加工許可命令MPCc及びMPC-fを先行加工プログラムNP1のブロッ クN70、N80の前段にそれぞれ挿入すると共に、加 工許可待命令PWC-c及びPWC-fを後続加工プロ グラムNP2のブロックN30、N40の前段にそれぞ れ挿入する。

【0031】加工許可命令MPC-d~MPC-fは、 各種の記号で指示できるが、例えばドル記号と職別数字 との組合わせ「\$1~\$4」のコードで入力され、加工 50 許可待命令PWC-d~PWC-fも各種の記号で指示できるが、例えば円記号と識別数字との組合わせ「¥1~¥4」のコードで入力される。このようにして左右の加工ユニットLM、RMを単独に運転して加工することを想定して作成された単独運転用の第1及び第2NCプログラムNP1、NP2が両加工ユニットの協調運転用に修正され、協調運転用プログラムNP1R、NP2Rが作成される。

【0032】この協調情報付加処理の後、図4に示すよ うに、第4段階として第2のデバグDBG2が実行され る。このデバグDBG2においては、上記のように修正 された協調運転のための第1及び第2NCプログラムNP 1 R 及び N P 2 R を同時並行的に C N C 装置 5 0 に実行 させ、左右の加工ユニットLM、RMが協調運転される 状態での両NCプログラNP1R、NP2Rム中のバグ を除去する。単独加工用のプログラムNP1、NP2に ついて第2段階でバグの除去が完了しているため、この 第4段階で発見されるバグは、協調運転のための協調情 報付加処理に起因するものと判断でき、このためこの第 4段階における第2のデバグDBG2は容易に行うことが できる。なお、修正された加工プログラムNP1R、N P2RがCNC装置50により実行されるとき、同装置 は各 \$ 記号を解読する毎に職別数字が対応する¥記号、 つまり加工許可待命令PWCを解除し、この¥記号の次 段のブロックについて、前述したNC実行処理62を開 始する。

【0033】本発明方法の主たる特徴は、上述したよう に、左右の加工ユニットLM、RMを協調運転するNC プログラムを作成する場合に、両加工ユニットを単独運 転するための各々のユニット用の単独加工プログラムN P1、NP2を最初作成し、次の段階においてこれら単 独加工プログラムを協調運転用に協調情報を付加するプ ロセスを含む。この場合、協調運転用に修正されたそれ ぞれのNCプログラムNP1R、NP2Rは、協調運転 のための協調情報を含むが別個のプログラムとして維持 されるので、一方の加工ユニット (例えばLM) が故障 した場合には、他方の加工ユニット (RM) 用に作成し そのまま保存される単独運転用のプログラム (NP2) を使用するか、或いはこのユニット用の協調運転用のプ ログラム(NP2R)から協調運転のために付加した情 報(PWC)を除去した後にこのプログラムを使用して 他方の加工ユニットにより単独運転で加工を行うことが できる利点がある。 本発明方法は、単独運転用加工プ ログラムNP1、NP2を作成した後にこれらプログラ ムのバグ除去処理DBG1を実行し、また協調運転用加 エプログラムNP1R、NP2Rを作成した後にさらに バグ除去処理DBG2を実行するようにし、バグの抽出 及び除去を容易にした点を付加的な特徴の1つとしてい

【0034】協調情報付加処理64は、オペレータ又は

プログラマが入出力装置54を操作して行うマニュアル 処理でもよいが、本発明はこの付加処理をCNC装置5 0に実行させるソフトウエアをCPU51のシステムプ ログラムSTMに組み入れたことを他の付加的な特徴と している。この付加処理64をCNC装置50に実行さ せて自動化を図ることにより、NCプログラム作成にお けるオペレータへの負担は、単に各加工ユニットLM、 RMを単独で運転する場合と同程度になり、2台の加工 ユニットLM、RMを協調運転する場合の従来プログラ ム作成方法に付随する困難性、プログラムエラーの誘発 10 を排除できると云った顕著な技術的前進が実現される。 【0035】図7は、図3に示す協調情報付加処理64 の一部を構成する干渉防止処理のフローチャートであ る。単独運転用のNCプログラムNP1、NP2がメモ リー52に記憶されている状態で、オペレータが入出力 装置54によりこの処理の実行命令を入力すると、CP U51がこの処理を開始する。先ず、ステップS1で左 右の加工ユニットLM、RMのどちらが先行して加工動 作を実行するか否か判定される。この判定は、NCプロ グラムNP1、NP2の何れか一方又は両方の2番目以 20 降の各データブロックのX軸目標値をチェックすること によりなされる。具体的には、X軸目標値が自己の起点 に復帰する方向に変遷する加工ユニットを先行加工ユニ ットと判定し、自己の起点から順次遠ざかる方向に変遷 する加工ユニットを後続加工ユニットと判定する。図5 のプログラム例では、第1NCプログラムNP1は複数 の加工個所 d, g, c, f, b, e, aのX軸目標値が 順次起点側に復帰するので、これを実行する左加工ユニ ットLMを先行加工ユニットと判定し、また第2NCプ ログラムNP2は複数の加工個所d, g, c, f, b, e, aのX軸目標値が順次起点から離れるので、これを 実行する右加工ユニットRMを後続加工ユニットと判定 する。

【0036】左加工ユニットLMが先行加工と判定され ると、第1及び第2NCプログラムNP1、NP2をそれ ぞれ記憶するメモリー領域ML、MRを被比較領域B及 び比較基準領域Aとして設定する (ステップS2)。逆 に、右加工ユニットRMが先行加工と判定されると、メ モリー領域ML、MRを比較基準領域A及び被比較領域 Bとして設定する(ステップS3)。次に、両領域A及 びBのアドレスAi及びBiをそれら領域の最初のアド レスにセットする (ステップS4)。 図では初期値を零 番地として表わしているが、これらの番地はそれぞれ両 領域A及びBの最初の番地に相当する。続いて、両アド レスAi及びBiに記憶されるNCデータブロックが読 出され(ステップS5及びS6)、これらブロック中の X軸目標値から左右の主軸ヘッド31、32の干渉を判 定する(ステップS7)。つまり、これら目標値の位置 に左右の主軸ヘッド31、32が同時に位置決めされる と仮定し、その場合に両主軸ヘッド31、32が物理的 50 に接触或いは衝突するか否か判定する。この判定は、具体的には、両主軸へッド31、32がそれぞれ左右の起点間の予め測定済みの距離XTからこれら起点を原点とする絶対送り位置XL、XRを減算し、その差が所定の干渉限界値Kより小さいときは干渉有り、大きいときは干渉無しと判定する。なお、左右の加工ユニット用のNCプログラムNP1、NP2中のX軸目標値は、それぞれ自己の起点を零点としこの零点からの相手側へ向かう移動量を正の絶対量として定義される。

0 【0037】干渉ありの場合、被比較領域アドレスBiが1番地増加され(ステップS8)、この新番地のデータブロックが最終プロック(EOB)であるか否か判定される(ステップS9)。最終プロックでないとき、その新番地のデータブロックが読出され(ステップS6)、これと比較基準領域アドレスAiのデータブロックとに基づいて干渉チェックが実行される(ステップS7)。このように、後続加工ユニット用の各NCデータブロックを比較基準とし、これを先行加工ユニット用の全てのNCデータブロック(被比較ブロック)と順次比り較する。

【0038】図5のプログラム例では、右主軸ヘッド32がd位置でタップ加工を行う時、ドリル加工を行う左主軸ヘッド31がd,g,c,f,b,e,aのどの位置で干渉するかをチェックするようにステップS6~S9が繰り返し実行される。これにより、干渉有りと判断される場合は、単に被比較領域アドレスBiを順次増加させ、第1NCプログラムNP1のデータプロックをN10、N20、N30、N40・・・と変えて行く。そして、被比較領域アドレスBiのデータプロックがb位置でのドリル加工を定義するものに変わる時、XT-XL-XR>Kの関係となって干渉無しと判定される(ステップS7)。

【0039】干渉無しと判定されるとき、比較基準アド レスAiの前段、つまりd位置でのタップ加工用データ ブロックN10の前段に第1番目の許可待命令¥1が挿 入され、被比較アドレスBiの前段、つまりb位置での ドリル加工用データプロックN50の前段に第1番目の 許可命令\$1が挿入される(ステップS10)。この処 理の後、比較基準アドレスAiが1番地進められ(ステ ップS11)、この更新された比較基準アドレスAiが 最終データブロックか否か判定される (ステップS1 2)。最終プロックでないとき、被比較アドレスBiを 初期値にクリアし (ステップS13)。その後ステップ S5に復帰し、更新された比較基準アドレスAiのNC データブロックを読出し、後続加工用の第2NCプログ ラムNP2の2番目のタップ加工用のデータブロックと 先行加工用の第1NCプログラムNP1の各データブロ ックとの比較を上述したように実行する。

【0040】このように処理することにより、図5の加工例では、g位置のタップ加工とe位置のドリル加工の

16

同時加工を許容するように、これらの加工を定義するデータブロックの前段に第2許可待命令¥2と第2許可命令\$2がそれぞれ挿入され、c位置のタップ加工とa位置のドリル加工を定義するデータブロックの前段に第3許可待命令¥3と第3許可命令\$3がそれぞれ挿入され、さらにf位置でのタップ加工を定義するデータブロックを先行加工動作する左加工ユニットLMの原位置復帰データブロックの前段に第4許可待命令¥4と第4許可命令\$4がそれぞれ挿入される。尚、図7のフローチャートではステップS9で最終プロックと判定されるときは、ステップS13の後にステップS5に復帰するようにしているが、ステップS9でYESと判定されるときは、それ以上の処理を省略するため破線で示すようにこの制御フローを終了するようにしてもよい。

【0041】次に、回転テーブル41の各割出位置にお いて左右の加工ユニットLM、RMが協調してワークW を加工する場合のプログラム作成方法を図8~図10を 参照して説明する。図8は、それぞれ個別に作成される 左右の加工ユニット用の単独加工用の第1NCプログラ ムNP1と第2NCプログラムNP2とワークWの割出 面L1~L3との関係を示す説明図である。各NCプロ グラムNP1、NP2は、ワークWの1つの加工面を加 工する1群のデータブロックの前段にその加工面を主軸 ヘッド31、32に向けるためのテーブル割出命令が独 立したデータブロックとして定義されている。具体的に は、ワークWの第1加工面L1を主軸ヘッド31、32 と対面する加工位置へ割り出す1つのデータブロック、 第1加工面 L 1 のための 1 群のデータブロック、第2加工 面 L 2を加工位置へ割り出す1つのデータブロック、第 2加工面L2のための1群のデータブロック、第3加工 面L3を加工位置へ割り出す1つのデータブロック、第 3加工面L3のための1群のデータブロックと続き、そ してワークの搬出準備として最後に第1加工面L1を再 び加工位置へ割り出す1つのデータブロックとで構成さ れる。

【0042】ワークWの同一加工面を加工するための各 1群のデータブロックは、例えば、図5及び図6を参照 して説明したプログラムNP1、NP2に相当する。し かし、この段階では、図5及び図6に示す加工許可命令 \$1、\$2・・・及びこれと対をなす加工許可待命令¥ 40 1、¥2・・・は未だ挿入されていない。好ましくは、 公知のパレット交換装置を用いて回転デーブル41上に ワークパレットを自動交換する形式のものとする場合で は、各NCプログラムNP1、NP2の最前段にパレット 投入命令が独立したデータブロックとして定義され、 最終段にパレット搬出命令が独立したデータブロックと して定義される。

【0043】このように作成される単独加工用の各NC プログラムNP1、NP2には、テーブル割出動作の同 一順位に回転テーブル41を同一の位置に割り出す命令 が重複して定義されることになる。CNC装置50が一方のNCプログラムに従って回転テーブル41を1つの位置に割出すように命令を与えた後に、他方のNCプログラムに従って同一の位置へ割出すように駆動回路DUBが命令されると、割出動作上のエラーを生じる。このため、これら単独加工用のNCプログラムNP1及びNP2を協調動作のために修正する必要があり、CNC装置50は図3の協調情報付加処理64を実行する。

【0044】図9は、CNC装置50が実行する協調情 報付加処理64全体の概要を説明する説明図である。具 体的には、この付加処理64は、概略3つの処理からな る。第1の処理は、加工面が同一のデータブロック群に 基づき先行加工ユニット及び後続加工ユニットを前述し た図7のステップS1と同様な処理により判別し、後続 加工する一方の加工ユニット用のデータブロック群の前 段にあるテーブル割出命令IA~IC及びテーブル戻し のための最後の割出命令IDを無効にすると共に、各デ ータブロック群の前段に割出完了待命令 I W C を挿入す る処理である。図9のプログラム例では、左右の加工ユ ニット用の第1及び第2NCプログラムNP1、NP2 は、いずれも3つの同一の割出位置で加工動作を実行す る第1~第3プログラム部LP1~LP3、RP1~RP 3で構成され、第1NCプログラムNP1のプロブラム 部LP1~LP3は、左加工ユニットLMの加工動作を プロブラム部RP1~RP3に従う右加工ユニットRM のそれらに対して先行させるようにプロブラムされてい る。従って、このプログラム例では、左加工ユニットレ MのNCプログラムNP1中に指定される割出命令と重 複する割出命令 IA, IB, IC, IDが全て除去され るか、無効にされる。また、最後の割出命令IDを除く 無効にされた各割出命令IA, IB, ICの次段に割出 完了待命令 I W C が挿入される。好適には、この処理で は、残したテーブル割出命令IA~ICの各々の次段 に、対応する前記割出完了待命令IWCを解除する割出 待解除命令MICを挿入する。

【0045】協調情報付加処理64の第2の処理は、同一加工面において左右の加工ユニットLM、RMの加工助作が全て完了しない限り回転テーブル41の次の割出命令を実行しないようにする加工完了待命令MWCとこれを解除する加工待解除命令MMCを追加することからなる。

【0046】具体的には、一方のNCプログラムに残される回転テーブルを次の割出位置に割出すための各割出命令IB,IC及びIDの前段の1ブロックに他方のNCプログラムによるその割出位置での加工完了を確認する加工完了待命令MWCを解除する加工待解除命令MMCを他方のNCプログラムに挿入する。第3の処理は、同一加工面を左右の加工ユニットLM、RMが協調して加工動作する場合に左右の主軸ヘッド31、32同士の干渉を防止す

るための対応する1群のNCデータブロック間での加工 許可待命令と加工許可命令の挿入処理であり、この処理 は図5~図7を参照して上述したように実行される。

【0047】テーブル割出命令IA、IB、IC及びIDを左加エユニット用の第1NCプログラムNP1に残してテーブル割出動作をこのプログラムにより制御するようにしたので、第2の処理では、プログラム部RP1、RP2、RP3に従う加工の完了に待機する加工完了待命令MWCを対応するプログラム部LP1、LP2、LP3の各々の次段に挿入する。また、加工完了待命令MWCを解除する加工待解除命令MMCを対応するプログラム部RP1、RP2、RP3の各々の次段に挿入する。第3の処理では、対応するプログラム部のデータブロック群に、協調運転のための加工許可待命令PWC及び加工許可命令MPCを前述したように付加する。【0048】図9のプログラム例とは異なって第2NCプログラムNP2のプログラム例とは異なって第2NCプログラムNP2のプログラム例とは異なって第2NCプログラム

プログラムNP2の一部のプログラム部、例えばRP2 を先行動作のためのものとする場合では、第1の処理に おいて同プログラム部RP2の割出命令IBを残すと共 に次段に鎖線で示すように割出待解除命令MICを挿入 20 し、一方、第1NCプログラムNP1の対応するプロブ ラム部LP2の割出命令IBを除去又は無効にすると共 にこの割出命令に続くデータブロック群Lcの前段に鎖 線で示すように割出完了待命令 I WCを挿入する。さら に第2の処理において、加工完了待命令MWCを第2プ ログラム部RP2の次段に、加工待解除命令を第2プロ グラムLP2の次段に、それぞれ鎖線で示すように挿入 する。これにより、回転テーブル41の割出命令は、図 9に示すように一方のNCプログラムNC1のみから与 えるようにすることもできるが、この割出命令を与える プログラム部をプログラム部毎に変えるようにし、先行 加工動作する加工ユニット、つまり左右の加工ユニット LM、RMが分担する作業を略均等にすることもでき る。

【0049】図10は、前述した第1~第3の処理を含む協調情報付加処理64をCNC装置50のCPU51に実行させるためのフローチャートを示す。この処理64の実行がオペレータにより命令されると、先ず単独加工用の第1及び第2NCプログラムNP1、NP2が割出命令単位で分割される(ステップS21)。具体的には、図9で破線で囲んで示すように、各プログラムは、1つの割出命令とこれに続く1以上のプログラム部が1つのグループとして分割され、各グループのNCデータを記憶する先頭のメモリーアドレスが記憶される。次に、分割数Dnが設定され(ステップS22)、図9のプログラム例では、Dn=3と設定される。

【0050】続いて、処理グループポインタPnが初期値"1"にセットされ(ステップS23)、以降の処理の対象を第1番目のプログラム部としてLP1, RP1を指定する。この後、ポインタPnが分割数Dnを超え 50

たか否か、つまり全てのグループについて処理が完了し たか否か判定され(ステップS24)、完了のときこの フローチャートに基づく処理が終了する。協調情報付加 処理64が未完了のとき、ポインタPnで特定される第 1番目の割出位置について第1及び第2NCプログラムN P1、NP2が共にプログラム部を有しているか判定さ れ(ステップS25)、一方しかプロブラム部がないと き、つまりそのテーブル割出位置では一方の加工ユニッ トのみの加工動作がプログラムされていると判定される とき、ステップS34ヘジャンプし、ここでポインタP nに1を加算して2番目のプログラム部を指定させた 後、ステップS24へ復帰する。このため、テーブル4 1の各割出位置において一方の加工ユニットのみが単独 で加工動作するようにプログラムされる場合では、この 割出位置を指定するプログラム部に対しては何らの修正 も行われない。

【0051】しかしながら、各割出位置において左右の 加工ユニットLM、RMが加工動作を行うようにするた めプログラム部が両NCプログラムNP1、NP2に存 在する場合では、どちらの加工ユニットが加工動作を先 行するのかが判定される (ステップS26)。この判定 は、図7のステップS1における処理と同様にして行わ れる。左加工ユニットLMを先行すると判定されると き、右加工ユニットRM用のプログラム部RP1の割出 命令IAが削除又は無効にされ(ステップS27)、こ の割出命令IAの次段に割出完了待命令IWCが挿入さ れると共に、残された割出命令IAの次段に割出解除命 令MICが挿入される(ステップS28)。さらに、左 加工ユニットLM用のプログラム部LP1の末尾に右加 エユニットRMの前記プログラム部RP1に従う加工動 作の完了を確認する加工完了待命令MWCが挿入される と共に、プログラム部RP1の末尾に加工待解除命令M MCが挿入される(ステップS29)。逆に、右加工ユ ニットRMを先行すると判定されるとき、左加工ユニッ トLM用のプログラム部LP1の割出命令 I Aが削除又 は無効にされ(ステップS30)、この割出命令 IAの 次段に割出完了待命令 I WCが挿入されると共に、プロ グラム部RP1の残された割出命令IAの次段に割出解 除命令MICが挿入される(ステップS31)。さらに プログラム部RP1の末尾に加工完了待命令MWCが挿 入されると共に、プログラム部LP1の末尾に加工解除 命令MMCが挿入される(ステップS32)。

【0052】ステップS29又はS32の後、前述した 干渉防止処理が図7のフローチャートに基づいて実行され(ステップS33)、これにより左右の加工ユニット LM、RM用のプログラム部LP1とRP1は、これら がCNC装置50により実行されるとき、左右の加工ユニットしM、RMが協調動作されて先行するユニットの 加工動作の終側の一部と後続する加工ユニットの前側の 一部とが両主軸ヘッド31、32がX軸方向で干渉しな いような状態で同時並行的に実行するように修正される。干渉防止処理S33が完了すると、ポインタPnは進められ(ステップS34)、これにより次の修正対象が2番目のプログラム部LP2、RP2に特定され、これらプログラム部LP2、RP2についてステップS25~S33が再度実行される。2番目のプログラム部LP2、RP3に対する協調情報付加処理の後、ポインタPnが3番目のプログラム部LP3、RP3を指定する(ステップS34)ので、再びステップS25~S33が実行されるとき、これら3番目のプログラム部LP3、RP3が修正され、回転テーブル41の割出に関する協調情報が図9のように付加される。

[0053]

【発明の効果】以上詳述したように、請求項1の発明に よれば、先行する一方の主軸ヘッドが複数の加工個所を 順次加工するための複数のデータブロックからなる先行 加工プログラムと後続する他方の主軸ヘッドが前記複数 の加工個所又は別の複数の加工個所を順次加工するため の複数のデータブロックからなる後続加工プログラムと をそれぞれ個別に作成し、その後先行及び後続加工プロ グラムの両方に協調動作のための協調情報を付加するよ うにしたので、各主軸ヘッドが単独で実行すべき加工プ ログラムの作成は通常の単一主軸ヘッド工作機械におけ る加工プログラムの作成と同様に比較的容易に作成で き、また協調運転のための協調情報の付加処理は両主軸 ヘッドの干渉のみを考慮してこの干渉を回避するための 協調情報を必要個所に挿入することにより達成されるの で、プログラム作成上の誤りを容易に排除でき、全体と してプログラムの作成が容易となる。

【0054】好適には、請求項2に記載されるように、前記協調運転のための協調情報付加処理を、工作機械を制御するCNC装置に実行させるようし、加工プログラム作成者への負担を単独運転用のプログラムの作成のみに軽減し、プログラムエラーの発生する機会が減少される。さらに好適には、請求項3に記載されるように、単独運転用の加工プログラムを作成した後にこれらプログラムに含まれるバグを除去し、このバグ除去を行った単独運転用加工プログラムに協調情報を付加して修正すると共にその後協調運転ブログラム上のバグを除去するようにしたので、各運転時における不具合が単独運転用プログラム中に含まれるバグによるものか或いは協調運転プログラム中に含まれるバグによるものかと云った観点でオペレータがバグを特定する作業が容易となり、全体としてバグの除去を容易かつ短時間で行えるようになる。

【0055】さらに好適には、請求項4に記載されるように、前記協調情報は、後続加工プログラムの前半部の実行を待機させる加工許可待命令を後続加工プログラムの前半部に挿入すると共に、加工許可待命令を解除する加工許可命令を先行加工プログラムの後半部に挿入する

ようにしたので、両主軸ヘッドの加工動作の一部を両ヘッドが干渉しないような状態で並行動作でき、加工能率が向上される。請求項5の発明によれば、回転テーブルの割出順序の同一順位に同一割出位置を指定する割出命令が両加工プログラムに重複する場合には両加工プログラムの一方からその重複する割出命令を削除するようにしたので、2つの加工プログラムが同時期に同一割出位置へ回転テーブルを割り出すような制御上の干渉が排除され、回転テーブルの割出制御における誤動作が排除される。

20

【0056】好適には、請求項6に記載されるように、 重複する一方の割出命令の削除に関連して、割出命令が 無効にされた加工プログラムの前段に割出完了待命令を 挿入し、また、この加工プログラムに基づく加工動作の 完了を確認するための加工完了待命令を割出命令が無効 にされなかった加工プログラムの次段に挿入するように したので、2つの主軸へッドの加工動作がそれぞれの加 エプログラムに従って異なる時点で開始され異なる時点 で終了されても、それら加工プログラムに基づく2台の 主軸へッドの加工動作が完了するまでは何れか一方の加 工動作が先に完了しても回転テーブルはその割出位置に 維持され、回転テーブルの誤動作が排除される。

【図面の簡単な説明】

【図1】本発明の加工プログラム作成方法を実施する2 主軸ヘッド工作機械の概略を示す正面図。

【図2】前記工作機械の制御システムを示すプロック線 図。

【図3】図2に示すCPUが実行する処理を説明するための機能プロック図。

30 【図4】本発明方法の概要手順を説明する説明図。

【図5】本発明方法が適用されるプログラムの1例を示す説明図。

【図6】本発明方法が適用されるプログラムの別の例を 示す説明図。

【図7】前記CPUが実行する干渉防止処理ルーチンの 詳細を示すフローチャート。

【図8】回転テーブルを使用する場合のプログラムの1 例を示す説明図。

【図9】図8のプログラム例における協調情報付加処理 を説明する説明図。


【図10】回転テーブルを使用する場合において前記C PUが実行する協調情報付加処理ルーチンの詳細を示す フローチャート。

【符号の説明】


LM: 左加工ユニット、 RM: 右加工ユニット、 3 1、3 2: 主軸ヘッド、 41: 回転テーブル、 T: 工具、 W: ワーク、 50: CNC装置、51: CPU、 52: メモリー、 56: 駆動装置、 NP1、NP2: 第1及び第2NCプログラム(先行及び後続加工NCプログラム)、 DBG1、DBG2: 第1及び

第2デバグ処理、 64:協調情報付加処理。


【図1】




【図2】



[図8]




【図3】



【図4】 【図7】 NP1 NP2 干涉防止処理 R侧先行 L侧先行 作成 作成 先行はL/R? NC NC S2 プログラム プログラム DBG1 1 2 A=MR, B=ML A=ML, B=MR デバグ デバグ A | =0, B | =0 A I のNCデータ読出 S5 自動修正実施 NC プログラム プログラム BiのNCデータ誘出 協調情報付加 XT-XL-XR<K 2 干渉有り? S8 NP2R NP1R A I の前段に許可待指令追加 B I の前段に許可指令追加 B i = B i + 1 デバグ (同時実行確認) / DBG2 BI=EOB? AI=AI+1 NO YES NO A I=EOB? B 1 = 0 END

【図5】



W 穴あけの場合 穴加工 穴加工 g加工許可待 N10 g加工 N10 d加工 加工許可待 N20 f加工 N20 c加工 N30 e加工 N30 b加工 **PWC** g加工許可 MPC (¥1~¥2) N40 戻り N40 a加工 (\$1~\$2)

NP2

(→NP2R)

加工許可 "


NP1

(→NP1R)

N50 戻り

【図6】

【図9】



【図10】

